

HUNTER TRUCK

HUNTER JERSEY PETERBILT
454 NORTH BROADWAY ST
PENNSVILLE, NJ 08070
P: (856) 299-5010
F: (856) 299-5020

BILL TO
JIM COMLY - 36296
PENNSVILLE NJ 08070

DELIVER TO
JIM COMLY - 36296
PENNSVILLE NJ 08070
P: 000-0000

SERVICE ESTIMATE: E206000203

DATE ARRIVED		DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE		
04/10/2019 7:27:28AM			SRET	R MCGINNIS	CASH	EST		
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2015	PETERBILT	CONVENTIONAL	1NPSLH0X4FD205035	9	2,819	7/24/2014	75027290	368096

JOB #1 34-000 LIGHTING - SYSTEM

COMPLAINT LIGHTING - SYSTEM
WHEN PERFORMING INSPECTIONS, FOUND THAT THE FRONT MARKER LAMP BULBS AND RIGHT REAR MARKER LAMPS ARE INOP

CAUSE LIGHTS

CORRECTION WHILE PERFORMING INSPECTIONS, FOUND FRONT AND RIGHT REAR MARKER LAMP BULBS INOP. SIDE MARKER LAMPS ON CHASSIS ARE OPERATIONAL, WILL VERIFY POWER AND GROUND TO THE INDIVIDUAL BULBS, AND IF NO ISSUES FOUND WILL REPLACE BLOWN BULBS AND VERIFY PROPER OPERATION.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/L92-6041-0100	HARNESS-LH MARKER	40.09	40.09
1	206P/P54-6169	LAMP-MARKER/TURN INDICATOR LED	55.37	55.37
	LABOR 34-000-24	LIGHTING – SYSTEM - REPAIR		125.00

Parts: \$95.46 Labor: \$125.00 Misc: \$5.50 Sublet: \$0 \$225.96

JOB #2 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM
DURING VEHICLE INSPECTIONS, FOUND DRIVERS SIDE STEP PANEL TO BE DAMAGED AND PASSENGER SIDE MISSING

CAUSE STEP PANELS

CORRECTION PERFORMED INSPECTIONS, FOUND DRIVERS SIDE STEP DAMAGED AND PASSENGER SIDE MISSING, RECOMMEND REPLACEMENT. WOULD NEED TO GO TO BODY MANUFACTURER FOR STEPS.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		250.00
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50

Parts: \$0 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$255.50

ESTIMATE

HUNTER TRUCK

SERVICE ESTIMATE: E206000203

JOB #3 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM
DURING VEHICLE INSPECTION, FOUND LEFT 1/4 FENDER MISSING AND RIGHT FENDER DAMAGED
CAUSE QUARTER FENDERS
CORRECTION DURING INSPECTIONS, FOUND FRONT RIGHT FRONT QUARTER FENDER DAMAGED AND LEFT QUARTER FENDER MISSING. RECOMMEND REPLACEMENT

THE FOLLOWING IS AN ESTIMATE TO REPLACE THE QUARTER FENDERS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		250.00
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/L33-6027	SKIRT-FENDER,365 SFFA	273.70	273.70
1	206P/L33-6027R	SKIRT-FENDER,365 SFFA	273.70	273.70

Parts: \$547.40 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$802.90

JOB #4 13-000 BRAKES - AIR SYSTEM

COMPLAINT BRAKES - AIR SYSTEM
DURING INSPECTIONS FOUND BRAKE PEDAL STICKING
CAUSE BRAKE PEDAL PIN
CORRECTION DURING VEHICLE INSPECTIONS, FOUND BRAKE PEDAL STICKING. COMMON CAUSE OF BRAKE PEDALS STICKING ARE BRAKE PEDAL PINS BEING CORRODED OR POSSIBLE FAILED BRAKE VALVE.

THE FOLLOWING IS AN ESTIMATE TO REPLACE THE BRAKE PEDAL PIN

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
	LABOR 13-000-24	BRAKES – AIR SYSTEM - REPAIR		250.00
1	206P/238888BXW	PIN-IDLER *D	9.06	9.06

Parts: \$9.06 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$264.56

JOB #5 13-000 BRAKES - AIR SYSTEM

COMPLAINT BRAKES - AIR SYSTEM
DURING VEHICLE INSPECTIONS, FOUND ABS LIGHT ACTIVE
CAUSE WHEEL SPEED SENSORS
CORRECTION DURING VEHICLE INSPECTIONS, FOUND ABS FAULTS FOR BOTH DRIVE AXLE WHEEL SPEED SENSORS. CHECKED SENSORS FOR SIGNS OF DAMAGE OR OBVIOUS WIRING FAILURES. NO ISSUES FOUND. ROOT CAUSE COULD BE A SENSOR, ABS WIRING HARNESS, OR ABS MODULE. ADDITIONAL DIAGNOSTICS WILL BE NEEDED TO FIND ROOT CAUSE OF FAILURE.

THE FOLLOWING IS AN ESTIMATE TO DIAG ABS LIGHT. ADDITONAL PARTS AND LABOR WILL BE REQUIRED ONCE FAILURE IS IDENTIFIED.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
	LABOR 13-000-24	BRAKES – AIR SYSTEM - REPAIR		250.00
2	206P/K051959BXW	SENSOR-WHEEL SPEED *D	62.21	124.42

Parts: \$124.42 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$379.92

HUNTER TRUCK

SERVICE ESTIMATE: E206000203

JOB #6 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM
DURING VEHICLE INSPECTIONS, FOUND BOTH WINDSHIELDS ARE CRACKED
CAUSE WINDSHIELDS
CORRECTION DURING INSPECTIONS FOUND BOTH WINDSHIELDS CRACKED. RECOMMEND REPLACEMENT.

THE FOLLOWING IS AN ESTIMATE TO REPLACE BOTH WINDSHIELDS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		375.00
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
1	206P/20-14898-20L	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/20-14898-20R	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/28-00236-0000	SEAL - BUTYL 27 FT ROLL	5.13	5.13

Parts: \$226.27 Labor: \$375.00 Misc: \$10.50 Sublet: \$0 \$611.77

JOB #7 44-000 FUEL - SYSTEM

COMPLAINT FUEL - SYSTEM
DURING INSPECTIONS, FOUND FUEL TANKS LOW ON FUEL
CAUSE FUEL
CORRECTION CHECKED UNIT OVER FOR FUEL LEAKS. HAVE VERIFIED THE FUEL LEAK IS BETWEEN THE FUEL SHUTOFF VALVE AT THE TANK TO THE ENGINE. WHEN SHUTTING OFF THE MANUAL VALVES AT THE TANK, FUEL LEAK DISSAPATES QUICKLY. FUEL SYSTEM WILL NEED ADDITIONAL DIAGNOSTICS TO VERIFY ROOT CAUSE. WOULD NEED TO GO TO BODY MANUFACTURER FOR REPAIR

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE

Parts: Labor: Misc: Sublet:

TERMS OF SALE

- 1) All sales are cash, unless other arrangements have been made. If charging, all amounts are due and payable net ten prox (Due by the 10th of the month following billing). No discounts permitted.
- 2) All past due amounts are subject to a service charge of 1 ½ % per month (18% per annum) on all past due balances.
- 3) No returns on electrical. No returns on special order items or items not returnable to the manufacturer. A restocking charge of 15% will apply on all other returns. Returns must be made within 30 days to receive credit.
- 4) Cores must be returned within 30 days to receive credit.
- 5) The seller hereby certifies that these goods were produced in compliance with all applicable requirements of sections 6, 7 and 12 of the Fair Labor Standards Act of 1938, as amended and of the regulations and orders of the administrator or wage and hour division issues under section 14 thereof.
- 6) By providing sales tax exemption number, customer certifies he is exempt from any sales or occupation tax and agrees if he is ruled to be not exempt by taxing authorities he will be responsible for any tax assessment made by the state of PA or another taxing authority and agrees to reimburse seller for any amount now due or becoming due, including penalties and interest, if assessed. In addition, buyer agrees to pay costs of pat due collection, including reasonable attorney's fees.
- 7) NO REFUND WITHOUT THIS NOTICE

WARRANTY

ANY WARRANTIES ON THE PRODUCTS SOLD ARE AVAILABLE ONLY FROM THE MANUFACTURER OR REBUILDER OF SAID PRODUCTS.
THE SELLER AGREES TO PASS TO CUSTOMER ANY AVAILABLE WARRANTIES. THE SELLER MAKES NO WARRANTIES OF ANY PRODUCTS SOLD AND AUTHORIZES NO PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THE PRODUCTS SHOW.
THE SELLER IS NOT RESPONSIBLE FOR LABOR ON PARTS NOT INSTALLED BY OUR SHOP.

LABOR	\$1,500.00
PARTS	\$1,002.61
MISC	\$38.00
SUBLET	\$0.00
SUBTOTAL	\$2,540.61
SHOP SUPPLIES	\$0.00
MISC SUPPLIES	\$0.00
TAX	\$168.32
TOTAL	\$2,708.93

Please Remit Payment to:

HUNTER JERSEY PETERBILT
PO BOX 820849
PHILADELPHIA, PA 19182-0849

AUTHORIZED BY _____ DATE _____