

HUNTER TRUCK

HUNTER JERSEY PETERBILT
454 NORTH BROADWAY ST
PENNSVILLE, NJ 08070
P: (856) 299-5010
F: (856) 299-5020

BILL TO
JIM COMLY - 36296
PENNSVILLE NJ 08070

DELIVER TO
JIM COMLY - 36296
PENNSVILLE NJ 08070
P: 000-0000

SERVICE ESTIMATE: E206000207

DATE ARRIVED		DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE		
04/10/2019 7:29:40AM			SRET	R MCGINNIS	CASH	EST		
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2015	PETERBILT	CONVENTIONAL	1NPSLH0X5FD205030	4	10,265		75027287	379618

JOB #1 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM
DURING WALK AROUND FOUND LEFT FRONT 1/4 FENDER AND LIGHT MISSING
CAUSE FRONT 1/4 FENDER
CORRECTION DURING INSPECTIONS, FOUND QUARTER FENDER MISSING. WOULD NEED TO INSTALL NEW 1/4 FENDER AND LIGHT

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-09	CAB – SYSTEM - TROUBLESHOOT		250.00
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/L33-6027	SKIRT-FENDER,365 SFFA	273.70	273.70
1	206P/L92-6041-0100	HARNESS-LH MARKER	40.09	40.09
1	206P/P54-6169	LAMP-MARKER/TURN INDICATOR LED	55.37	55.37

Parts: \$369.16 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$624.66

JOB #2 45-000 ENGINE - SYSTEM

COMPLAINT ENGINE - SYSTEM
CHECK ENGINE LIGHT
CAUSE MISFIRE FAULT CODES
CORRECTION NEED TO TROUBLESHOOT CYLINDER 5 MISFIRE FAULTS FURTHER. WILL PERFORM CYLINDER LEAK DOWN TEST, SPARK TEST, INSPECT IGNITION SYSTEM AND IF NO ISSUES FOUND, WILL NEED TO REPLACE A SET OF SPARK PLUGS. FOLLOWING REPLACEMENT, WILL PERFORM ROAD TEST TO VERIFY NO FURTHER ISSUES PRESENT.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
6	206C/4309391	KIT,SPARK PLUG	45.83	274.98
	LABOR 45-000-09	ENGINE – SYSTEM - TROUBLESHOOT		472.50

Parts: \$274.98 Labor: \$472.50 Misc: \$10.50 Sublet: \$0 \$757.98

ESTIMATE

HUNTER TRUCK

SERVICE ESTIMATE: E206000207

JOB #3 34-000 LIGHTING - SYSTEM

COMPLAINT LIGHTING - SYSTEM
DURING WALK AROUND FOUND RIGHT FRONT 1/4 FENDER LIGHT OUT, RIGHT FOG LIGHT INOP, RIGHT REAR TAIL/TURN OUT, FRONT TURN SIGNAL BULBS OUT.

CAUSE LIGHTS

CORRECTION WILL NEED TO CHECK POWERS AND GROUNDS TO ALL LAMPS TO VERIFY GOOD POWER SOURCE. IF WIRING FAILURES ARE FOUND, WILL NEED TO REPAIR AND REPLACE THE FAILED BULBS AND VERIFY PROPER OPERATION.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
2	206P/1156BULB	BULB-AUTO/TRUCK S8 12.8V SC BA	0.92	1.84
1	206P/16-09790-001	LIGHT-FOG RECTANGULAR W/H9415	192.87	192.87
1	206P/44030R	KIT-LIGHT LED S/T/T 6DIO W/ *D	26.46	26.46
1	206P/L92-6033-0100	HARNESS-WIRE-JUMPER	39.88	39.88
1	206P/P54-6169	LAMP-MARKER/TURN INDICATOR LED	55.37	55.37
	LABOR 34-000-24	LIGHTING - SYSTEM - REPAIR		250.00

ESTIMATE
Parts: \$316.42 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$571.92**JOB #4 02-000 CAB - SYSTEM**

COMPLAINT CAB - SYSTEM
DURING WALK AROUND FOUND BOTH WINDSHIELDS DAMAGED

CAUSE WINDSHIELD

CORRECTION DURING INSPECTIONS, FOUND BOTH WINDSHIELDS CRACKED. WILL NEED TO REMOVE AND REPLACE BOTH WINDSHIELDS.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
1	206P/20-14898-20L	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/20-14898-20R	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/28-00236-0000	SEAL - BUTYL 27 FT ROLL	5.13	5.13
	LABOR HT-022	REPLACE ONE WINDSHIELD (TWO PIECE)		375.00

Parts: \$226.27 Labor: \$375.00 Misc: \$10.50 Sublet: \$0 \$611.77

JOB #5 13-000 BRAKES - AIR SYSTEM

COMPLAINT BRAKES - AIR SYSTEM
DURING INSPECTIONS, FOUND ABS LIGHT INOP

CAUSE FRONT WHEEL SPEED SENSOR

CORRECTION CONNECTED TO ABS MODULE AND FOUND FAULTS FOR FORWARD WSS OPEN CIRCUIT. WILL NEED TO PERFORM RESISTANCE CHECKS ON WSS AND REPLACE AS NEEDED. WILL THEN NEED TO ROADTEST UNIT AND VERIFY LIGHT DOES NOT RETURN.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
	LABOR 13-000-24	BRAKES - AIR SYSTEM - REPAIR		250.00
1	206P/K051959BXW	SENSOR-WHEEL SPEED *D	62.21	62.21

Parts: \$62.21 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$317.71

HUNTER TRUCK

SERVICE ESTIMATE: E206000207

JOB #6 45-000 ENGINE - SYSTEM

COMPLAINT ENGINE - SYSTEM
DURING INSPECTIONS, FOUND MULTIPLE OIL LEAKS PRESENT

CAUSE OIL LEAKS

CORRECTION MULTIPLE ENGINE OIL LEAKS PRESENT, APPEARS TO COME FROM OIL PAN. WILL NEED TO STEAM CLEAN ENGINE, ADD DYE TO ENGINE OIL AND PERFORM BLACKLIGHT TEST TO VERIFY ALL COMPONENTS THAT ARE LEAKING OIL AND CREATE AN UPDATED ESTIMATE FOR THE REPAIRS NEEDED.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/EB1RSS	(RS) CLEANER-ENGINE BRITE 16*D	5.42	5.42
	LABOR 45-000-09	ENGINE - SYSTEM - TROUBLESHOOT		135.00

Parts: \$5.42 Labor: \$135.00 Misc: \$5.50 Sublet: \$0 \$145.92

JOB #7 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM
DURING INSPECTIONS, FOUND RIGHT SIDE STEP MISSING

CAUSE MISSING STEP

CORRECTION DURING INSPECTIONS, FOUND STEP MISSING ON PASSENGER TANK PANEL. NEED TO REPLACE P/S STEP AND SECURE.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-09	CAB - SYSTEM - TROUBLESHOOT		62.50
1	206P/11-03942-0750	STEP-FUEL TANK ALUM 750MM	223.16	223.16

Parts: \$223.16 Labor: \$62.50 Misc: \$0 Sublet: \$0 \$285.66

TERMS OF SALE

- 1) All sales are cash, unless other arrangements have been made. If charging, all amounts are due and payable net ten prox (Due by the 10th of the month following billing). No discounts permitted.
- 2) All past due amounts are subject to a service charge of 1 ½ % per month (18% per annum) on all past due balances.
- 3) No returns on electrical. No returns on special order items or items not returnable to the manufacturer. A restocking charge of 15% will apply on all other returns. Returns must be made within 30 days to receive credit.
- 4) Cores must be returned within 30 days to receive credit.
- 5) The seller hereby certifies that these goods were produced in compliance with all applicable requirements of sections 6, 7 and 12 of the Fair Labor Standards Act of 1938, as amended and of the regulations and orders of the administrator or wage and hour division issues under section 14 thereof.
- 6) By providing sales tax exemption number, customer certifies he is exempt from any sales or occupation tax and agrees if he is ruled to be not exempt by taxing authorities he will be responsible for any tax assessment made by the state of PA or another taxing authority and agrees to reimburse seller for any amount now due or becoming due, including penalties and interest, if assessed. In addition, buyer agrees to pay costs of pat due collection, including reasonable attorney's fees.
- 7) NO REFUND WITHOUT THIS NOTICE

WARRANTY

ANY WARRANTIES ON THE PRODUCTS SOLD ARE AVAILABLE ONLY FROM THE MANUFACTURER OR REBUILDER OF SAID PRODUCTS. THE SELLER AGREES TO PASS TO CUSTOMER ANY AVAILABLE WARRANTIES. THE SELLER MAKES NO WARRANTIES OF ANY PRODUCTS SOLD AND AUTHORIZES NO PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THE PRODUCTS SHOW. THE SELLER IS NOT RESPONSIBLE FOR LABOR ON PARTS NOT INSTALLED BY OUR SHOP.

LABOR	\$1,795.00
PARTS	\$1,477.62
MISC	\$43.00
SUBLET	\$0.00
SUBTOTAL	\$3,315.62
SHOP SUPPLIES	\$0.00
MISC SUPPLIES	\$0.00
TAX	\$219.66
TOTAL	\$3,535.28

Please Remit Payment to:

HUNTER JERSEY PETERBILT

PO BOX 820849

PHILADELPHIA, PA 19182-0849

AUTHORIZED BY _____ DATE _____