

HUNTER JERSEY PETERBILT 454 NORTH BROADWAY ST PENNSVILLE, NJ 08070 P: (856) 299-5010

P: (856) 299-5010 F: (856) 299-5020

BILL TO JIM COMLY - 36296 PENNSVILLE NJ 08070 DELIVER TO JIM COMLY - 36296 PENNSVILLE NJ 08070 P: (000) 000-0000

SERVICE ESTIMATE: E206000206

DAT	E ARRIVED	DATE INVOICE SALES TYPE ADVISOR TERMS		TERMS	MS CUSTOMER REFERENCE			
04/10/2019	7:29:25AM		SRET	R MCGIN	INIS	CASH	EST	
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2015	PETERBILT	CONVENTIONAL	1NPSLH0X0FD205033	7	10,316		75027289	334948

JOB #1 33-000 IGNITION - SYSTEM

COMPLAINT IGNITION - SYSTEM

DURING WALK AROUND FOUND ISSUE WITH STARTING CIRCUIT

CAUSE BODY COMPANY ISSUE

CORRECTION NARROWED ISSUE DOWN TO FUEL SYSTEM. WOULD NEED TO SEND TO BODY COMPANY TO FURTHER DIAG

ISSUE

WOULD NEED TO SEND TRUCK TO BODY COMPANY FOR DIAG ON FUEL SYSTEM

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE

Parts: Labor: Misc: Sublet:

JOB #2 17-000 TIRES - SYSTEM

COMPLAINT TIRES - SYSTEM

DURING WALK AROUND FOUND TIRES ON LIFT AXLE AND FRONT REAR LOW

CAUSE TIRES

CORRECTION WOULD NEED TO REPLACE TIRES ON FRONT REAR AND LIFT AXLE/

THE FOLLOWING IS AN ESTIMATE TO REPLACE WORN TIRES

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
4	AMC	DRIVE TIRE (GT GAM835) 11R24.5	574.00	2,296.00
2	AMC	LIFT AXLE TIRE (GT GAM835) 315/80R22.5	640.99	1,281.98
	LABOR 17-000-24	TIRES – SYSTEM - REPAIR		625.00

Parts: \$0 Labor: \$625.00 Misc: \$3,588.48 Sublet: \$0 \$4,213.48



JOB #3 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING WALK AROUND FOUND RIGHT SIDE STEP AND BRACKETS MISSING

CAUSE STEPS

CORRECTION WOULD NEED TO INSTALL NEW STEPS AND BRACKETS

THE FOLLOWING IS AN ESTIMATE FOR LABOR TO INSTALL STEPS AND BRACKETS. WOULD NEED TO GET PARTS

FROM BODY MANUFACTURE

Г	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
		LABOR 02-000-24	CAB – SYSTEM - REPAIR		62.50
Г	1	206P/11-03942-0750	STEP-FUEL TANK ALUM 750MM	223.16	223.16

Parts: \$223.16 Labor: \$62.50 Misc: \$0 Sublet: \$0 \$285.66

JOB #4 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING WALK AROUND FOUND BOTH FRONT 1/4 FENDERS AND LIGHTS IN FENDERS MISSING

CAUSE FENDERS

CORRECTION WOULD NEED TO INSTALL BOTH FRONT 1/4 FENDERS AND LIGHTS.

THE FOLLOWING IS AN ESTIMATE TO REPLACE FRONT 1/4 FENDERS AND LIGHTS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		250.00
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/L33-6027	SKIRT-FENDER,365 SFFA	273.70	273.70
1	206P/L33-6027R	SKIRT-FENDER,365 SFFA	273.70	273.70
1	206P/L92-6033-0100	HARNESS-WIRE-JUMPER	39.88	39.88
1	206P/L92-6041-0100	HARNESS-LH MARKER	40.09	40.09
2	206P/P54-6169	LAMP-MARKER/TURN INDICATOR LED	55.37	110.74

Parts: \$738.11 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$993.61

JOB #5 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING WALK AROUND FOUND HOOD DAMAGED

CAUSE HOOD

CORRECTION WOULD NEED TO INSTALL NEW HOOD

THE FOLLOWING IS AN ESTIMATE TO REPLACE THE HOOD

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		625.00
1	AMC3	ASSIGNED MAINTENANCE COST 3	18.00	18.00
1	AMC	PAINT	2,000.00	2,000.00
2	206P/L11-6133	BRACKET-GUIDE HOOD	181.71	363.42
2	206P/L11-6178	BRACKET-HOOD GUIDE 365 STL	230.61	461.22
1	206P/L29-6073-1200020	HOOD-365 SF NON-PRIMED TILT W/	7,206.15	7,206.15
1	206P/L48-6135	PIVOT-HOOD, LH ASSY	602.05	602.05
1	206P/L48-6136	PIVOT-HOOD, RH ASSY	602.05	602.05

Parts: \$9,234.89 Labor: \$625.00 Misc: \$2,018.00 Sublet: \$0 \$11,877.89



JOB #6 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING WALK AROUND FOUND BUMPER DAMAGED

CAUSE BUMPER

CORRECTION WOULD NEED TO INSTALL NEW BUMPER

THE FOLLOWING IS AN ESTIMATE TO INSTALL NEW BUMPER

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		125.00
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/TU08V0010-02NS	PB 10GA CHRM, 16"TAPER *D	413.58	413.58

Parts: \$413.58 Labor: \$125.00 Misc: \$5.50 Sublet: \$0 \$544.08

JOB #7 18-000 HUBS/BEARINGS - SYSTEM

COMPLAINT HUBS/BEARINGS - SYSTEM

DURING WALK AROUND FOUND BOTH HUB CAPS LEAKING

CAUSE HUB CAPS

CORRECTION WOULD NEED TO INSTALL NEW HUB CAPS ON STEER AXLE

THE FOLLOWING IS AN ESTIMATE TO REPLACE HUB CAPS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 18-000-24	HUBS/BEARINGS – SYSTEM - REPAIR		62.50
2	206P/1613CHR	HUBCAP *D	28.20	56.40

Parts: \$56.40 Labor: \$62.50 Misc: \$0 Sublet: \$0 \$118.90

JOB #8 45-000 ENGINE - SYSTEM

COMPLAINT ENGINE - SYSTEM

DURING WALK AROUND FOUND OIL LEAKS FROM OIL PAN AND FILTER HOUSING

CAUSE OIL LEAKS

CORRECTION WOULD NEED TO STEAM ENGINE AND RESEAL OIL LEAKS

THE FOLLOWING IS AN ESTIMATE TO STEAM ENGINE, REPLACE OIL PAN GASKET AND OIL FILTER HEAD

GASKETS AND RUN ENGINE TO CHECK FOR LEAKS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
3	206C/875572	NAT GAS PAIL 15W40	76.66	229.98
1	206P/4975069CUM	GASKET-OIL PAN	162.78	162.78
1	206P/82194PTX	(PX) GASKET MAKER-ULTRA GRY *D	8.56	8.56
1	206P/LF14000NNFLG	(FL) FILTER *D	38.93	38.93
	LABOR 45-000-24	ENGINE – SYSTEM - REPAIR	-	405.00

Parts: \$440.25 Labor: \$405.00 Misc: \$10.50 Sublet: \$0 \$855.75



JOB #9 22-000 DRIVE AXLE - SYSTEM

COMPLAINT DRIVE AXLE - SYSTEM

DURING WALK AROUND FOUND FORWARD REAR LEAKING

CAUSE CARRIER

CORRECTION WOULD NEED TO RESEAL REAR CARRIER

THE FOLLOWING IS AN ESTIMATE TO RESEAL THE CARRIER

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
1	206P/82194PTX	(PX) GASKET MAKER-ULTRA GRY *D	8.56	8.56
	LABOR 22-000-24	DRIVE AXLE – SYSTEM - REPAIR		500.00

Parts: \$8.56 Labor: \$500.00 Misc: \$10.50 Sublet: \$0 \$519.06

JOB #10 44-000 FUEL - SYSTEM

COMPLAINT FUEL - SYSTEM

DURING WALK AROUND FOUND FUEL TANK MOUNTING CROSSMEMBER MISSING BOLTS

CAUSE MISSING BOLTS

CORRECTION WOULD NEED TO INSTALL NEW BOLTS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC	BOLTS	25.00	25.00
	LABOR 44-000-24	FUEL – SYSTEM - REPAIR		62.50

Parts: \$0 Labor: \$62.50 Misc: \$25.00 Sublet: \$0 \$87.50

JOB #11 13-000 BRAKES - AIR SYSTEM

COMPLAINT BRAKES - AIR SYSTEM

DURING WALK AROUND HEARD MULTIPLE AIR LEAKS

CAUSE AIR LEAKS

CORRECTION WOULD NEED TO LOCATE AND FIX AIR LEAKS AS NEEDED

THE FOLLOWING IS AN ESTIMATE TO FIND AND REPAIR ALL LEAKS AS NEEDED

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	AMC	MISC AIR FITTINGS	50.00	50.00
	LABOR 13-000-24	BRAKES – AIR SYSTEM - REPAIR		250.00

Parts: \$0 Labor: \$250.00 Misc: \$55.50 Sublet: \$0 \$305.50

JOB #12 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING WALK AROUND FOUND BOTH WINDSHIELDS DAMAGED

CAUSE WINDSHIELDS

CORRECTION WOULD NEED TO REMOVE AND REPLACE BOTH WINDSHIELDS

THE FOLLOWING IS AN ESTIMATE TO REPLACE BOTH WINDSHIELDS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		375.00
1	206P/20-14898-20L	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/20-14898-20R	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/28-00236-0000	SEAL - BUTYL 27 FT ROLL	5.13	5.13

Parts: \$226.27 Labor: \$375.00 Misc: \$0 Sublet: \$0 \$601.27



JOB #13 27-000 TRANS AUTO - SYSTEM

COMPLAINT TRANS AUTO - SYSTEM

DURING WALK AROUND FOUND TRANS LIGHT ON

CAUSE FAULT CODES

CORRECTION WOULD NEED TO CONNECT TO ALLISON, RETRIEVE FAULTS AND DIAG AS NEEDED.

THE FOLLOWING IS AN ESTIMATE TO DIAG TRANS LIGHT. WOULD NEED ADDITIONAL TIME AND PARTS ONCE

FAILURE IS IDENTIFIED

С	YTÇ	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
		LABOR 27-000-24	TRANS AUTO – SYSTEM - REPAIR		250.00

Parts: \$0 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$255.50

JOB #14 13-000 BRAKES - AIR SYSTEM

COMPLAINT BRAKES - AIR SYSTEM

DURING WALK AROUND FOUND ABS LIGHT ON

CAUSE FAULT CODES

CORRECTION WOULD NEED TO CONNECT TO ABS MODULE, RETRIEVE FAULTS AND DIAG AS NEEDED.

THE FOLLOWING IS AN ESTIMATE TO DIAG ABS FAULTS. WOULD REQUIRE ADDITIONAL PARTS AND LABOR

ONCE FAILURE IS IDENTIFIED

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
	LABOR 13-000-24	BRAKES – AIR SYSTEM - REPAIR		250.00

Parts: \$0 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$255.50

JOB #15 34-000 LIGHTING - SYSTEM

COMPLAINT LIGHTING - SYSTEM

DURING WALK AROUND FOUND REVERSE LIGHT INOP

CAUSE LIGHT

CORRECTION WOULD NEED TO REPLACE LIGHT

THE FOLLOWING IS AN ESTIMATE TO REPLACE THE REVERSE LIGHT

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	206P/40204	LAMP-MODEL 40, CLEAR, 12V *D	6.20	6.20
	LABOR 34-000-24	LIGHTING – SYSTEM - REPAIR	-	62.50

Parts: \$6.20 Labor: \$62.50 Misc: \$0 Sublet: \$0 \$68.70



ESTIMATE

TERMS OF SALE

- 1) All sales are cash, unless other arrangements have been made. If charging, all amounts are due and payable net ten prox (Due by the 10th of the month following billion). No discounts permitted
- 2) All past due amounts are subject to a service charge of 1 ½ % per month (18% per annum) on all past due balances.

 No returns on electrical. No returns on special order items or items not returnable to the manufacturer. A restocki
- 3) No returns on electrical. No returns on special order items or items not returnable to the manufacturer. A restocking charge of 15% will apply on all other returns. Returns must be made within 30 days to receive credit.
- Returns must be made within 30 days to receive
 Cores must be returned within 30 days to receive credit.
- 5) The seller hereby certifies that these goods were produced in compliance with all applicable requirements of sections 6, 7 and 12 of the Fair Labor Standards Act of 1938, as amended and of the regulations and orders of the administrator or wage and hour division issues under section 14 thereof.
- 6) By providing sales tax exemption number, customer certifies he is exempt from any sales or occupation tax and agrees if he is ruled to be not exempt by taxing authorities he will be responsible for any tax assessment made by the state of PA or another taxing authority and agrees to reimburse seller for any amount now due or becoming due, including penalties and interest, if assessed. In addition, buyer agrees to pay costs of pat due collection, including reasonable attorney's fees.
- 7) NO REFUND WITHOUT THIS NOTICE

WARRANTY

ANY WARRANTIES ON THE PRODUCTS SOLD ARE AVAILABLE ONLY FROM THE MANUFACTURER OR REBUILDER OF SAID PRODUCTS. THE SELLER AGREES TO PASS TO CUSTOMER ANY AVAILABLE WARRANTIES. THE SELLER MAKES NO WARRANTIES OF ANY PRODUCTS SOLD AND AUTHORIZES NO PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THE PRODUCTS SHOW. THE SELLER IS NOT RESPONSIBLE FOR LABOR ON PARTS NOT INSTALLED BY OUR SHOP.

TOTAL	\$22,372.48
TAX	\$1,390.08
MISC SUPPLIES	\$0.00
SHOP SUPPLIES	\$0.00
SUBTOTAL	\$20,982.40
SUBLET	\$0.00
MISC	\$5,729.98
PARTS	\$11,347.42
LABOR	\$3,905.00

Please Remit Payment to: HUNTER JERSEY PETERBILT PO BOX 820849 PHILADELPHIA, PA 19182-0849

AUTHORIZED BY	 DATE	