

HUNTER TRUCK

HUNTER JERSEY PETERBILT
454 NORTH BROADWAY ST
PENNSVILLE, NJ 08070
P: (856) 299-5010
F: (856) 299-5020

BILL TO
JIM COMLY - 36296
PENNSVILLE NJ 08070

DELIVER TO
JIM COMLY - 36296
PENNSVILLE NJ 08070
P: 000-0000

SERVICE ESTIMATE: E206000210

DATE ARRIVED		DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE		
04/10/2019 7:33:55AM			SRET	R MCGINNIS	CASH	EST		
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2015	PETERBILT	CONVENTIONAL	1NPSLH0X7FD205028	2	9.765		75027293	323425

JOB #1 34-000 LIGHTING - SYSTEM

COMPLAINT LIGHTING - SYSTEM
DURING INSPECTIONS, FOUND MULTIPLE LIGHTS INOP

CAUSE LIGHTS

CORRECTION DURING INSPECTIONS, FOUND REVERSE LIGHT AND CENTER BRAKE LIGHT INOP. COMMON FAILURES WOULD BE BULBS. WILL NEED TO CHECK POWER AND GROUND TO LIGHTS AND VERIFY NO ISSUES. IF POWER AND GROUND ARE CORRECT, WILL NEED TO REPLACE FAILED BULBS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	206P/40204	LAMP-MODEL 40, CLEAR, 12V *D	6.20	6.20
1	206P/44030R	KIT-LIGHT LED S/T/T 6DIO W/ *D	26.46	26.46
	LABOR 34-000-24	LIGHTING – SYSTEM - REPAIR		125.00

Parts: \$32.66 Labor: \$125.00 Misc: \$0 Sublet: \$0 \$157.66

JOB #2 45-000 ENGINE - SYSTEM

COMPLAINT ENGINE - SYSTEM
DURING INSPECTIONS, PULLED FAULT CODES

CAUSE CEL

CORRECTION DURING INSPECTIONS, PULLED ECM INFORMATION AND FAULT CODES. CODES PRESENT FOR MULTIPLE CYLINDER MISFIRE AND OLDER CODES WITH MULTIPLE COUNTS OF ENGINE INTAKE AIR MASS FLOW. BOTH CODES COULD BE CAUSED BY FUEL SYSTEM RELATED FAILURES AND REQUIRE ADDITIONAL DIAGNOSTICS TO VERIFY ROOT CAUSE OF FAILURE.

THE FOLLOWING IS AN ESTIMATE TO DIAG CEL. WILL REQUIRE ADDITIONAL PARTS AND LABOR ONCE FAILURE IS IDENTIFIED.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
	LABOR 45-000-24	ENGINE – SYSTEM - REPAIR		270.00

Parts: \$0 Labor: \$270.00 Misc: \$5.50 Sublet: \$0 \$275.50

HUNTER TRUCK

SERVICE ESTIMATE: E206000210

JOB #3 13-000 BRAKES - AIR SYSTEM

COMPLAINT BRAKES - AIR SYSTEM
DURING INSPECTIONS, FOUND ABS LIGHT ACTIVE

CAUSE ABS LIGHT

CORRECTION DURING INSPECTIONS, FOUND ABS LIGHT ACTIVE. PULLED FAULTS TO FIND CODES FOR WHEEL SPEED SENSORS. PERFORMED VISUAL INSPECTIONS ON ALL WIRING AND SENSORS, FINDING NO OBVIOUS SIGNS OF DAMAGE. ADDITIONAL DIAGNOSTICS WILL BE NEEDED TO FIND ROOT CAUSE OF FAILURE.

THE FOLLOWING IS AN ESTIMATE TO DIAG ABS FAULTS. ADDITONAL PARTS AND LABOR WILL BE NEEDED ONCE FAILURE IS IDENTIFIED

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
	LABOR 13-000-24	BRAKES – AIR SYSTEM - REPAIR		250.00

Parts: \$0 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$255.50

JOB #4 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM
DURING INSPECTIONS, FOUND P/S WINDSHIELD CRACKED

CAUSE WINDSHIELD

CORRECTION DURING INSPECTIONS, FOUND RIGHT SIDE WINDSHIELD CRACKED, RECOMMEND REPLACEMENT.

THE FOLLOWING IS AN ESTIMATE TO REPLACE THE RIGHT SIDE WINDSHIELD

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		187.50
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/20-14898-20R	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/28-00236-0000	SEAL - BUTYL 27 FT ROLL	5.13	5.13

Parts: \$115.70 Labor: \$187.50 Misc: \$5.50 Sublet: \$0 \$308.70

JOB #5 13-000 BRAKES - AIR SYSTEM

COMPLAINT BRAKES - AIR SYSTEM
DURING INSPECTIONS, FOUND AIR LEAKS EXCESSIVE

CAUSE AIR LEAKS

CORRECTION DURING INSPECTIONS, FOUND UNIT LEAKS DOWN AIR AT AN EXCESSIVE RATE WHEN ENGINE IS NOT RUNNING. ADDITIONAL DIAGNOSTICS WILL BE NEEDED TO REPAIR ALL AIR SYSTEM LEAKS

THE FOLLOWING IS AN ESTIMATE TO FIND AND REPAIR AIR LEAKS AS NEEDED

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	AMC	MISC FITTINGS	50.00	50.00
	LABOR 13-000-24	BRAKES – AIR SYSTEM - REPAIR		250.00

Parts: \$0 Labor: \$250.00 Misc: \$55.50 Sublet: \$0 \$305.50

HUNTER TRUCK

SERVICE ESTIMATE: E206000210

JOB #6 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM
DURING INSPECTIONS, FOUND BODY PANEL DAMAGES

CAUSE BODY PANELS

CORRECTION DURING INSPECTIONS FOUND FRONT BUMPER DAMAGED, HOOD FENDER DAMAGES, PASSENGER SIDE STEP MISSING AND FRONT QUARTER FENDERS MISSING. RECOMMEND REPLACEMENT.

THE FOLLOWING IS AN ESTIMATE TO REPLACE ABOVE ITEMS

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		1,000.00
1	AMC5	ASSIGNED MAINTENANCE COST 5	36.40	36.40
1	AMC	PAINT	2,000.00	2,000.00
2	206P/13-03662	STUD-SPRING HOOD 1/2-20NF STL	10.54	21.08
2	206P/13-03663	STUD-CABLE HOOD 1/2-20NF STL	8.27	16.54
2	206P/L11-6178	BRACKET-HOOD GUIDE 365 STL	230.61	461.22
1	206P/L29-6073-1200020	HOOD-365 SF NON-PRIMED TILT W/	7,206.15	7,206.15
1	206P/L33-6027	SKIRT-FENDER,365 SFFA	273.70	273.70
1	206P/L33-6027R	SKIRT-FENDER,365 SFFA	273.70	273.70
1	206P/L48-6135	PIVOT-HOOD, LH ASSY	602.05	602.05
1	206P/L48-6136	PIVOT-HOOD, RH ASSY	602.05	602.05
1	206P/TU08V0010-02NS	PB 10GA CHRМ, 16"ТAPER *D	413.58	413.58

Parts: \$9,870.07 Labor: \$1,000.00 Misc: \$2,036.40 Sublet: \$0 \$12,906.47

JOB #7 22-000 DRIVE AXLE - SYSTEM

COMPLAINT DRIVE AXLE - SYSTEM
DURING INSPECTIONS, FOUND FORWARD DRIVE AXLE LEAKS FLUID

CAUSE CARRIER HOUSING

CORRECTION DURING INSPECTIONS, FOUND FRONT DRIVE HOUSING LEAKING FLUID. OIL LEAK APPEARS TO BE FROM BETWEEN CARRIER AND HOUSING SURFACE. WILL NEED TO CLEAN REAR HOUSING AND RECHECK TO VERIFY LEAK, THEN REMOVE, RESEAL AND REINSTALL CARRIER.

THE FOLLOWING IS AN ESTIMATE TO RESEAL THE CARRIER

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
1	206P/82194PTX	GASKET MAKER-ULTRA GRY 3.5O *D	8.56	8.56
	LABOR 22-000-24	DRIVE AXLE – SYSTEM - REPAIR		500.00

Parts: \$8.56 Labor: \$500.00 Misc: \$10.50 Sublet: \$0 \$519.06

HUNTER TRUCK

SERVICE ESTIMATE: E206000210

ESTIMATE

TERMS OF SALE

- 1) All sales are cash, unless other arrangements have been made. If charging, all amounts are due and payable net ten prox (Due by the 10th of the month following billing). No discounts permitted.
- 2) All past due amounts are subject to a service charge of 1 ½ % per month (18% per annum) on all past due balances.
- 3) No returns on electrical. No returns on special order items or items not returnable to the manufacturer. A restocking charge of 15% will apply on all other returns. Returns must be made within 30 days to receive credit.
- 4) Cores must be returned within 30 days to receive credit.
- 5) The seller hereby certifies that these goods were produced in compliance with all applicable requirements of sections 6, 7 and 12 of the Fair Labor Standards Act of 1938, as amended and of the regulations and orders of the administrator or wage and hour division issues under section 14 thereof.
- 6) By providing sales tax exemption number, customer certifies he is exempt from any sales or occupation tax and agrees if he is ruled to be not exempt by taxing authorities he will be responsible for any tax assessment made by the state of PA or another taxing authority and agrees to reimburse seller for any amount now due or becoming due, including penalties and interest, if assessed. In addition, buyer agrees to pay costs of pat due collection, including reasonable attorney's fees.
- 7) NO REFUND WITHOUT THIS NOTICE

WARRANTY

ANY WARRANTIES ON THE PRODUCTS SOLD ARE AVAILABLE ONLY FROM THE MANUFACTURER OR REBUILDER OF SAID PRODUCTS. THE SELLER AGREES TO PASS TO CUSTOMER ANY AVAILABLE WARRANTIES. THE SELLER MAKES NO WARRANTIES OF ANY PRODUCTS SOLD AND AUTHORIZES NO PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THE PRODUCTS SHOW. THE SELLER IS NOT RESPONSIBLE FOR LABOR ON PARTS NOT INSTALLED BY OUR SHOP.

LABOR	\$2,582.50
PARTS	\$10,026.99
MISC	\$2,118.90
SUBLET	\$0.00
SUBTOTAL	\$14,728.39
SHOP SUPPLIES	\$0.00
MISC SUPPLIES	\$0.00
TAX	\$975.76
TOTAL	\$15,704.15

Please Remit Payment to:
HUNTER JERSEY PETERBILT
PO BOX 820849
PHILADELPHIA, PA 19182-0849

AUTHORIZED BY _____ DATE _____