

HUNTER JERSEY PETERBILT 454 NORTH BROADWAY ST PENNSVILLE, NJ 08070 P: (856) 200 5010

P: (856) 299-5010 F: (856) 299-5020

JIM COMLY - 36295 PENNSVILLE NJ 08070 DELIVER TO
JIM COMLY - 36295
PENNSVILLE NJ 08070
P: (000) 000-0000

## **SERVICE ESTIMATE: E206000204**

DA	TE ARRIVED	DATE INVOICE	SALES TYPE	ADVISOI	₹	TERMS	CUSTOMER RE	FERENCE
04/10/2019	9 7:27:50AM		SRET	R MCGIN	NIS	CASH	EST	
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT#	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2015	PETERBILT	CONVENTIONAL	1NPSLH0X9FD205029	3	0		75027291	308383

# JOB #1 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING INSPECTIONS, FOUND BOTH WINDSHIELDS ARE CRACKED

CAUSE WINSHIELDS

CORRECTION DURING INSPECTIONS, FOUND BOTH WINDSHIELDS CRACKED AND NEED REPLACED.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
1	206P/20-14898-20L	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/20-14898-20R	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/28-00236-0000	SEAL - BUTYL 27 FT ROLL	5.13	5.13
	LABOR HT-022	REPLACE ONE WINDSHIELD (TWO PIECE)		375.00

Parts: \$226.27 Labor: \$375.00 Misc: \$10.50 Sublet: \$0 \$611.77

# JOB #2 45-000 ENGINE - SYSTEM

COMPLAINT ENGINE - SYSTEM

DURING INSPECTIONS, FOUND ENGINE OIL LEAK PRESENT

CAUSE OIL PAN GASKET

CORRECTION DURING INSPECTIONS FOUND OIL LEAKING AROUND OIL PAN GASKET. RECOMMEND REPLACEMENT OF OIL

PAN GASKET.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
3	206C/875572	NAT GAS PAIL 15W40	76.66	229.98
1	206P/4975069CUM	GASKET-OIL PAN	162.78	162.78
1	206P/LF14000NNFLG	(FL) FILTER *D	38.93	38.93
	LABOR 45-000-24	ENGINE – SYSTEM - REPAIR		270.00

Parts: \$431.69 Labor: \$270.00 Misc: \$10.50 Sublet: \$0 \$712.19

**SERVICE ESTIMATE: E206000204** 



#### JOB #3 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING INSPECTIONS, FOUND DRIVERS SIDE WINDOW INOP

CAUSE DRIVERS SIDE WINDOW

CORRECTION DURING INSPECTIONS, FOUND DRIVERS SIDE WINDOW INOP. CHECKED FOR ANY BLOWN FUSES BUT NONE TO

NOTE WERE FAILED. COMMON FAILURES INCLUDE WIRING, WINDOW MOTOR, OR WINDOW SWITCH. WILL NEED TO VERIFY PROPER POWER AND GROUND TO WINDOW MOTOR, IF POWER IS PRESENT, WINDOW MOTOR

HAS FAILED AND WILL NEED REPLACED.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-09	CAB – SYSTEM - TROUBLESHOOT		187.50
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/R21-6009	REGULATOR-WINDOW ELEC LH	447.39	447.39

Parts: \$447.39 Labor: \$187.50 Misc: \$5.50 Sublet: \$0 \$640.39

# JOB #4 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING INSPECTIONS, FOUND FRONT BUMPER IS BENT

CAUSE BUMPER

CORRECTION DURING INSPECTIONS, FOUND FRONT BUMPER BENT, RECOMMEND REPLACEMENT. NEED TO REMOVE AND

REPLACE FRONT BUMPER.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		125.00
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/TU08V0010-02NS	PB 10GA CHRM, 16"TAPER *D	413.58	413.58

Parts: \$413.58 Labor: \$125.00 Misc: \$5.50 Sublet: \$0 \$544.08

## JOB #5 34-000 LIGHTING - SYSTEM

COMPLAINT LIGHTING - SYSTEM

DURING INSPECTIONS, FOUND MULTIPLE LIGHTS INOP

CAUSE LIGHTING

CORRECTION DURING INSPECTIONS, FOUND THE FOLLOWING LIGHTS INOP: RIGHT FRONT SIDE TURN SIGNAL, MULTIPLE

MARKER LAMP BULBS, RIGHT REAR REAR TURN SIGNALS, AND FOG LIGHT INOP. COMMON FAILURE OF THESE ITEMS WOULD BE BULBS, BUT COULD INCLUDE WIRING OR WATER INTRUSION INTO THE CONNECTORS. WILL NEED TO VERIFY PROPER POWER AND GROUND TO ALL LIGHTS, AND IF NO WIRING ISSUES ARE PRESENT, WILL NEED TO REPLACE FAILED BULBS. PLEASE NOTE IF ANY WIRING ISSUES ARE PRESENT, ADDITIONAL LABOR

MAY BE NEEDED FOR REPAIRS.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
2	206P/1157BULB	BULB-AUTO/TRUCK S8 12.8-14V DC	0.70	1.40
1	206P/L92-6033-0100	HARNESS-WIRE-JUMPER	39.88	39.88
1	206P/P54-6169	LAMP-MARKER/TURN INDICATOR LED	55.37	55.37
	LABOR 34-000-09	LIGHTING – SYSTEM - TROUBLESHOOT		250.00

Parts: \$96.65 Labor: \$250.00 Misc: \$10.50 Sublet: \$0 \$357.15



#### JOB #6 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING INSPECTIONS, FOUND LEFT QUARTER FENDER IS CRACKED AND LIGHT MISSING

CAUSE QUARTER FENDER

CORRECTION DURING INSPECTIONS, FOUND QUARTER FENDER AND LAMP DAMAGED. RECOMMEND REPLACEMENT.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 02-000-24	CAB – SYSTEM - REPAIR		125.00
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
1	206P/L33-6027	SKIRT-FENDER,365 SFFA	273.70	273.70

Parts: \$273.70 Labor: \$125.00 Misc: \$5.50 Sublet: \$0 \$404.20

## JOB #7 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING INSPECTIONS, FOUND P/S STEP TO BE MISSING

CAUSE STEP PANEL

CORRECTION DURING INSPECTIONS, FOUND P/S STEP PANEL TO BE MISSING, RECOMMEND REPLACEMENT.

G	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
		LABOR 02-000-09	CAB – SYSTEM - TROUBLESHOOT		62.50
	1	206P/11-03942-0750	STEP-FUEL TANK ALUM 750MM	223.16	223.16

Parts: \$223.16 Labor: \$62.50 Misc: \$0 Sublet: \$0 \$285.66

## JOB #8 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM

DURING INSPECTIONS, FOUND TAIL GATE TO BE BENT

CAUSE TAILGATE

CORRECTION DURING INSPECTIONS, FOUND TAIL GATE TO BE BENT. RECOMMEND REPLACEMENT. DUE TO TAILGATE BEING

A BODY COMPONENT, WOULD NEED TO GO TO THE BODY MANUFACTURER FOR REPLACEMENT.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE

Parts: Labor: Misc: Sublet:

# JOB #9 32-000 CRANKING - SYSTEM

COMPLAINT CRANKING - SYSTEM

DURING INSPECTIONS, FOUND BATTERIES WILL NOT HOLD CHARGE

CAUSE BATTERIES

CORRECTION DURING INSPECTIONS, FOUND BATTERIES WILL NOT HOLD A CHARGE, RECOMMEND REPLACEMENT.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
3	206P/YEL31STUD	BATTERY-YELLOW TOP D31T900 *D	431.44	1,294.32
	LABOR 32-000-24	CRANKING – CRANKING - REPAIR		187.50

Parts: \$1,294.32 Labor: \$187.50 Misc: \$5.50 Sublet: \$0 \$1,487.32



# **ESTIMATE**

#### TERMS OF SALE

- 1) All sales are cash, unless other arrangements have been made. If charging, all amounts are due and payable net ten prox (Due by the 10th of the month following
- All past due amounts are subject to a service charge of 1 ½ % per month (18% per annum) on all past due balances.
- 3) No returns on electrical. No returns on special order items or items not returnable to the manufacturer. A restocking charge of 15% will apply on all other returns. Returns must be made within 30 days to receive credit.
- Returns must be made within 30 days to receive
   Cores must be returned within 30 days to receive credit.
- 4) Cores must be returned within 30 days to receive credit.
  5. The selfer hereby certifies that these goods were produced in compliance with all applicable requirements of sections 6, 7 and 12 of the Fair Labor Standards Act of 1938, as amended and of the regulations and orders of the administrator or wage and hour division issues under section 14 thereof.
- 6) By providing sales tax exemption number, customer certifies he is exempt from any sales or occupation tax and agrees if he is ruled to be not exempt by taxing authorities he will be responsible for any tax assessment made by the state of PA or another taxing authority and agrees to reimburse seller for any amount now due or becoming due, including penalties and interest, if assessed. In addition, buyer agrees to pay costs of pat due collection, including reasonable attorney's fees.
- 7) NO REFUND WITHOUT THIS NOTICE

#### WARRANTY

ANY WARRANTIES ON THE PRODUCTS SOLD ARE AVAILABLE ONLY FROM THE MANUFACTURER OR REBUILDER OF SAID PRODUCTS. THE SELLER AGREES TO PASS TO CUSTOMER ANY AVAILABLE WARRANTIES. THE SELLER MAKES NO WARRANTIES OF ANY PRODUCTS SOLD AND AUTHORIZES NO PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THE PRODUCTS SHOW. THE SELLER IS NOT RESPONSIBLE FOR LABOR ON PARTS NOT INSTALLED BY OUR SHOP.

TOTAL	\$5,376.84
TAX	\$334.08
MISC SUPPLIES	\$0.00
SHOP SUPPLIES	\$0.00
SUBTOTAL	\$5,042.76
SUBLET	\$0.00
MISC	\$53.50
PARTS	\$3,406.76
LABOR	\$1,582.50

Please Remit Payment to: HUNTER JERSEY PETERBILT PO BOX 820849 PHILADELPHIA, PA 19182-0849

AUTHORIZED BY	 DATE	