

HUNTER TRUCK

HUNTER JERSEY PETERBILT
454 NORTH BROADWAY ST
PENNSVILLE, NJ 08070
P: (856) 299-5010
F: (856) 299-5020

BILL TO
JIM COMLY - 36296
PENNSVILLE NJ 08070

DELIVER TO
JIM COMLY - 36296
PENNSVILLE NJ 08070
P: 000-0000

SERVICE ESTIMATE: E206000213

DATE ARRIVED		DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER REFERENCE		
04/10/2019 9:35:39AM			SRET	R MCGINNIS	CASH	EST		
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2015	PETERBILT	CONVENTIONAL	1NPSLH0X6FD205036	10	0		75027294	333342

JOB #1 32-000 CRANKING - SYSTEM

COMPLAINT CRANKING - SYSTEM
DURING INSPECTIONS, FOUND BATTERIES TO NOT HOLD CHARGE
CAUSE BATTERIES
CORRECTION DURING INSPECTIONS, FOUND BATTERIES WOULD NOT HOLD A CHARGE. TESTED BATTERIES WITH MIDTRONICS BATTERY TESTER, FINDING BATTERIES FAILED. NEED TO REMOVE AND REPLACE BATTERIES.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
3	206P/YEL31STUD	BATTERY-YELLOW TOP D31T900 *D	431.44	1,294.32
	LABOR 32-000-09	CRANKING - CRANKING - TROUBLESHOOT		187.50

Parts: \$1,294.32 Labor: \$187.50 Misc: \$5.50 Sublet: \$0 \$1,487.32

JOB #2 02-000 CAB - SYSTEM

COMPLAINT CAB - SYSTEM
DURING WALK AROUND FOUND BOTH WINDSHIELDS DAMAGED
CAUSE WINDSHIELD
CORRECTION WOULD NEED TO REMOVE AND REPLACE BOTH WINDSHIELDS.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
1	206P/20-14898-20L	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/20-14898-20R	GLASS-WINDSHIELD ENCAPSULATED	110.57	110.57
1	206P/28-00236-0000	SEAL - BUTYL 27 FT ROLL	5.13	5.13
	LABOR HT-022	REPLACE ONE WINDSHIELD (TWO PIECE)		375.00

Parts: \$226.27 Labor: \$375.00 Misc: \$10.50 Sublet: \$0 \$611.77

HUNTER TRUCK

SERVICE ESTIMATE: E206000213

JOB #3 13-000 BRAKES - AIR SYSTEM

COMPLAINT BRAKES - AIR SYSTEM
DURING WALK AROUND FOUND TRUCK HAS MULTIPLE AIR LEAKS
CAUSE AIR LEAKS
CORRECTION WOULD NEED TO IDENTIFY AND REPAIR ALL LEAKS AS NEEDED.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
	LABOR 13-000-09	BRAKES – AIR SYSTEM - TROUBLESHOOT		125.00
4	206P/FG8390	(DC) FITTING-UNION #4J2494 S*D	7.41	29.64

Parts: \$29.64 Labor: \$125.00 Misc: \$5.50 Sublet: \$0 \$160.14

JOB #4 34-000 LIGHTING - SYSTEM

COMPLAINT LIGHTING - SYSTEM
DURING WALK AROUND FOUND MARKER LAMPS ON FRONT 1/4 FENDERS HAVE WIRES CUT AND ARE INOP, LEFT OF CENTER BRAKE RUNNING LIGHT IS INOP, FLASHERS ON BODY INOP.
CAUSE LIGHTING
CORRECTION WOULD NEED TO PERFORM EXTENSIVE WIRING CHECKS AND THEN REPAIR AS NEEDED, AND REPLACE FAILED BULBS.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	206P/44030R	KIT-LIGHT LED S/T/T 6DIO W/ *D	26.46	26.46
10	206P/CT05512	TIE-CABLE 120LB, 15.25" BLK	0.26	2.60
10	206P/HT21140	CONNECTOR-BUTT HTSHRKBL 16-14G	0.68	6.80
10	206P/HT21180	CONNECTOR-BUTT HTSHRKBL 22-18G	0.81	8.10
1	206P/L92-6033-0100	HARNESS-WIRE-JUMPER	39.88	39.88
1	206P/L92-6041-0100	HARNESS-LH MARKER	40.09	40.09
2	206P/P54-6169	LAMP-MARKER/TURN INDICATOR LED	55.37	110.74
	LABOR 34-000-09	LIGHTING – SYSTEM - TROUBLESHOOT		312.50

Parts: \$234.67 Labor: \$312.50 Misc: \$0 Sublet: \$0 \$547.17

JOB #5 45-000 ENGINE - SYSTEM

COMPLAINT ENGINE - SYSTEM
DURING WALK AROUND FOUND ENGINE LEAKS OIL
CAUSE OIL LEAKS
CORRECTION NEED TO STEAM ENGINE, RUN AND IDENTIFY ALL LEAKS AND THEN RESEAL AS NEEDED. OIL PAN GASKET IS LEAKING AND WILL NEED REPLACED. FOLLOWING REPLACEMENT AND STEAM CLEAN, WILL RECHECK FOR LEAKS AND UPDATE ESTIMATE AS REQUIRED.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
3	206C/875572	NAT GAS PAIL 15W40	76.66	229.98
1	206P/4975069CUM	GASKET-OIL PAN	162.78	162.78
1	206P/LF14000NNFLG	(FL) FILTER *D	38.93	38.93
	LABOR 45-000-24	ENGINE – SYSTEM - REPAIR		270.00

Parts: \$431.69 Labor: \$270.00 Misc: \$5.50 Sublet: \$0 \$707.19

HUNTER TRUCK

SERVICE ESTIMATE: E206000213

JOB #6 17-000 TIRES - SYSTEM

COMPLAINT TIRES - SYSTEM
DURING WALK AROUND FOUND FORWARD REAR TIRES TREAD LOW

CAUSE TIRES

CORRECTION NEED TO REMOVE AND REPLACE ALL DRIVE TIRES ON FORWARD REAR.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC2	ASSIGNED MAINTENANCE COST 2	10.50	10.50
4	AMC	DRIVE AXLE TIRE (GT GAM835) 11R24.5	574.00	2,296.00
	LABOR 17-000-09	TIRES – SYSTEM - TROUBLESHOOT		500.00

Parts: \$0 Labor: \$500.00 Misc: \$2,306.50 Sublet: \$0 \$2,806.50

JOB #7 44-000 FUEL - SYSTEM

COMPLAINT FUEL - SYSTEM
DURING WALK AROUND FOUND FUEL TANK COVER DAMAGED

CAUSE FUEL TANK COVER

CORRECTION WOULD NEED TO REMOVE AND REPLACE FUEL TANK COVER. NEED TO CONTACT BODY MANUFACTURE FOR PRICING.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
	LABOR 44-000-09	FUEL – SYSTEM - TROUBLESHOOT		125.00

Parts: \$0 Labor: \$125.00 Misc: \$5.50 Sublet: \$0 \$130.50

JOB #8 13-000 BRAKES - AIR SYSTEM

COMPLAINT BRAKES - AIR SYSTEM
DURING WALK AROUND FOUND ABS LIGHT ON

CAUSE ABS LIGHT

CORRECTION ABS LIGHT IS ACTIVE BUT CANNOT CONNECT TO BENDIX ECU. NEED TO DIAGNOSE WHY ABS MODULE NOT COMMUNICATING ON CAN NETWORK AND REPAIR AS NEEDED. ONCE CONNECTION IS ESTABLISHED, WOULD NEED TO CONNECT TO ABS MODULE, RETRIEVE FAULTS AND TROUBLESHOOT THE FAULTS AS NEEDED.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	AMC1	ASSIGNED MAINTENANCE COST 1	5.50	5.50
	LABOR 13-000-24	BRAKES – AIR SYSTEM - REPAIR		250.00
1	206P/MIN10	FUSE-10 AMP(5EA=1BOX)	1.11	1.11
1	206P/MIN5	FUSE-5 AMP	1.11	1.11

Parts: \$2.22 Labor: \$250.00 Misc: \$5.50 Sublet: \$0 \$257.72

HUNTER TRUCK

SERVICE ESTIMATE: E206000213

ESTIMATE

TERMS OF SALE

- 1) All sales are cash, unless other arrangements have been made. If charging, all amounts are due and payable net ten prox (Due by the 10th of the month following billing). No discounts permitted.
- 2) All past due amounts are subject to a service charge of 1 ½ % per month (18% per annum) on all past due balances.
- 3) No returns on electrical. No returns on special order items or items not returnable to the manufacturer. A restocking charge of 15% will apply on all other returns. Returns must be made within 30 days to receive credit.
- 4) Cores must be returned within 30 days to receive credit.
- 5) The seller hereby certifies that these goods were produced in compliance with all applicable requirements of sections 6, 7 and 12 of the Fair Labor Standards Act of 1938, as amended and of the regulations and orders of the administrator or wage and hour division issues under section 14 thereof.
- 6) By providing sales tax exemption number, customer certifies he is exempt from any sales or occupation tax and agrees if he is ruled to be not exempt by taxing authorities he will be responsible for any tax assessment made by the state of PA or another taxing authority and agrees to reimburse seller for any amount now due or becoming due, including penalties and interest, if assessed. In addition, buyer agrees to pay costs of pat due collection, including reasonable attorney's fees.
- 7) NO REFUND WITHOUT THIS NOTICE

WARRANTY

ANY WARRANTIES ON THE PRODUCTS SOLD ARE AVAILABLE ONLY FROM THE MANUFACTURER OR REBUILDER OF SAID PRODUCTS. THE SELLER AGREES TO PASS TO CUSTOMER ANY AVAILABLE WARRANTIES. THE SELLER MAKES NO WARRANTIES OF ANY PRODUCTS SOLD AND AUTHORIZES NO PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THE PRODUCTS SHOW. THE SELLER IS NOT RESPONSIBLE FOR LABOR ON PARTS NOT INSTALLED BY OUR SHOP.

LABOR	\$2,145.00
PARTS	\$2,218.81
MISC	\$2,344.50
SUBLET	\$0.00
SUBTOTAL	\$6,708.31
SHOP SUPPLIES	\$0.00
MISC SUPPLIES	\$0.00
TAX	\$444.43
TOTAL	\$7,152.74

Please Remit Payment to:
HUNTER JERSEY PETERBILT
PO BOX 820849
PHILADELPHIA, PA 19182-0849

AUTHORIZED BY _____ DATE _____