



Henry Drilling LLC
1110 Harpeth Industrial Ct.
Franklin, TN 37064
615-794-1784

www.henrydrillingandpump.com

HENRY DRILLING WELL INSPECTION REPORT

Client Information

Client Name: [REDACTED] Contact Number: [REDACTED]
Client Address: ~~7104 Goodard Rd Fairview~~ 7104 Goodard Rd Fairview
Client Email: [REDACTED]

Owner Information

Owner Name: [REDACTED] ☐ Occupied ☒ Vacant
Address: [REDACTED]
Owner Email: [REDACTED]

*The purpose of this inspection is to report the present 'as is' and visible condition of the system & its related components

System Information

1. Type of system:	<input checked="" type="checkbox"/> private <input type="checkbox"/> community
2. Pressure tank size or Model: V60	AO SMITH Aqua AIR
3. Operation of pump:	<input type="checkbox"/> satisfactory <input type="checkbox"/> unsatisfactory
4. Pressure found on tank: 20	(psi)
5. Pumping rate:	gallons per minute
6. Amps of pump:	amps <input type="checkbox"/> acceptable <input type="checkbox"/> unacceptable
7. Is well head visible?	<input checked="" type="checkbox"/> yes <input type="checkbox"/> no
8. Water treatment system?	type: <input type="checkbox"/> pitless <input checked="" type="checkbox"/> well seal
9. Water filtration?	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no type:
10. Leaks found?	<input type="checkbox"/> yes <input type="checkbox"/> no type:
11. Storage tank?	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no
12. Amps of pump in tank:	amps <input type="checkbox"/> acceptable <input type="checkbox"/> unacceptable
13. Water sample taken? YES or NO	Sent to lab? <input type="checkbox"/> yes <input checked="" type="checkbox"/> no

Notes or recommendations:

No electricity @ Well
ohmed pump @ well, checks good
Will need New Tank and Tank Kit
Will need New 1/2" Wire Bored from disconnect on PDL to Pressure Tank (Apex Soft)

Inspected by:

Date of Inspection:

Chris Harper, Blake